



545 E Algonquin Road, Suite H
Arlington Heights, IL 60005

Telephone: 847-439-5667
www.intertek.com

For Immediate Release: September 8, 2015

**INTERTEK WARNS OF INVALID/COUNTERFEIT INTERTEK REPORT
IDENTIFYING SHENZHEN LINPU ELECTRONICS MODELS LD-1, LD-2, JMP-1, JMP-2, JMP-3,
KMP-1, KMP-2, KMP-3, TGM15, TGM20, TGMT15, and TGMT20**

Intertek Testing Services notifies consumers, retailers and distributors that Intertek Authorization to Mark (ATM) with no date identifying for product models LD-1, LD-2, JMP-1, JMP-2, JMP-3, KMP-1, KMP-2, KMP-3, TGM15, TGM20, TGMT15, and TGMT20 is an invalid document and has been determined to be counterfeit.

These products have not been evaluated by Intertek. It is unknown if these products are in compliance with the applicable safety standards.

Document Information: Intertek Authorization to Mark (ATM)

Product: Ground Fault Circuit Interrupters

**Model: LD-1, LD-2, JMP-1, JMP-2, JMP-3, KMP-1, KMP-2, KMP-3, TGM15, TGM20,
TGMT15, and TGMT20**

Manufacturer: SHENZHEN LINPU ELECTRONICS

This notice only applies to the Intertek Report identifying product Ground Fault Circuit Interrupters Ground Fault Circuit Interrupters models LD-1, LD-2, JMP-1, JMP-2, JMP-3, KMP-1, KMP-2, KMP-3, TGM15, TGM20, TGMT15, and TGMT20. A copy of the cover page of the invalid counterfeit document is provided for reference.

Photos of Invalid/Counterfeit Documents:

